

## 5660-71-XX



for general repair and maintenance purposes as well as for the manufacture of equipment and tools Product info

Product info2 After complete hardening, can be machined (drilled,

milled, ground, etc.)

Temperature min. °C -50

Temperature max. °C +120

Part No.	Weigt gr
56607100	500 g